

HITENDRA CHHEDA & ASSOCIATES
ARCHITECTURAL & STRUCTURAL DESIGNERS

S. D. X-NORTH-81A, NEAR HOTEL SHIV REGENCY, GANDHIDHAM,
(M) 098 251 70410. E-MAIL: hitendrachheda_07@yahoo.com

Date : 25th October, 2023.

TO WHOMSOEVER IT MAY CONCERN

Description of site and location: Shree Swaminarayan Gurukul, DC-2 at Gandhidham.

Owner:- Shree Swaminarayan Gurukul, Gandhidham.

Name;-_Shree Swaminarayan Gurukul School Building

I certify that I have inspected the premises and reviewed it internally and externally on dt. 20-10-2023, the School Building (Ground + 2 Floor only) on Plot No. Swaminarayan Gurukul, DC-2 at Gandhidham owned by Shree Swaminarayan Gurukul, Gandhidham. I am of the opinion that the structure of the said premises appears in sound condition and that its stability will not be endangered by its continued use for which the building was intended.

I am possessing current registration to act as a Structural Designer vide Structural Engineer License No. GDA - SD - 28 of Gandhidham Development Authority.

The plans of School Building have been approved by Gandhidham Development Authority and constructed as per permission No. 27271/P dt.14-02-2004.

Plot Area = 9041.85 SQM

Covered area of school building on G.F. = 1075.05 SQM

Covered area of school building on F.F. = 1075.05 SQM

Covered area of school building on S.F. = 948.58 SQM


During the inspection it was observed that the said School Building is R.C.C. Framed Structure Building.


Year of construction is 2005.

Number of storeyes.- G+2

Basement - NO

Mezzanine - NO


PRESIDENT
SHREE SWAMI NARAYAN
GURUKUL, GANDHIDHAM


PRINCIPAL
Shree Swaminarayan Vidyalay
Gandhidham (Kutch)

Typical floor height.- 3.65 M
Types of Slabs.- Flat roof.
Surrounding of School.- Low rise buildings.
NO congested or market area.
Low Traffic Area.

During Inspection following points were noted:

- | | |
|---|-----|
| 1. Any changes subsequent to construction : | No |
| 2. Nearby open excavation: | No |
| 3. R.W. pipe outlets: | Yes |
| 4. Settlements: | No |
| 5. Cracks in Masonary walls: | No |

The Superstructure (R.C.C. Frame Structure):

- | | |
|--|-----|
| 1. Beam Cracks in column or beams: | No |
| 2. Cover spell: | No. |
| 3. Exposure reinforcement: | No |
| 4. Subsequent damage by user for taking
Pipes, conduits, hanging fans or any
Other fixtures: | No |
| 5. Crack in Slab: | No |
| 6. Swelling of concrete or plaster of slab: | No |
| 7. Corrosion of reinforcement: | No |
| 8. Loads in excess of design loads: | No |

This is to certify that the above is a correct representation of facts as given to me by the owner and as determined by me after Site Inspection to the best of my ability and judgment.

Er. HITENDRA CHHEDA
B.E. (civil)
License No. GDA-SD-28.
License valid upto 31-03-2025.
(Gandhidham Development Authority)
Date: 25th October, 2023.

[Signature]

Er. HITENDRA CHHEDA
B.E. (CIVIL) GOLD MEDALIST
REGISTERED ENGINEER

[Signature]
PRESIDENT
SHREE SWAMI NARAYAN
GURUKUL GANDHIDHAM

[Signature]
PRINCIPAL
Shree Swaminarayan Vidyalay
Gandhidham (Kutch)